

Wisconsin Department of Commerce PECFA Program

BID NUMBER: 06-53192-9999-07

PECFA number: 53192-9999-07
BRRTS number: 03-30-002258
Site Name: Wilmot Auto Service
Site Address: 11307 Fox River Road, Wilmot, WI 53192

Program contact: Nancy S. Kochis, Site Review Hydrogeologist
Program contact address: 101 West Pleasant Street, Suite 205
Milwaukee, WI 53212
Program contact phone: 414-220-5372
Program contact e-mail address: nkochis@commerce.state.wi.us

Submitted Questions and Responses

1. Has the DNR or DCOM specified how many times the two potable wells on the property must be sampled? If so, how many rounds of sampling of the potable wells are required?

A minimum of one round. Based on the sampling results, additional rounds may be warranted

2. Based on contaminant isoconcentrations lines of groundwater impacts found in the Site Investigation Report, PVOC impacts appear to be concentrated around the 4 newer gasoline USTs installed in 1990. In addition, groundwater impacts in the 3 leak detection wells located near these USTs increased substantially between 1993 and 1994. Does the DNR and DCOM believe that the source of the petroleum release has been removed?

The remedial system operated from March 1998 through February 1999. At this time, there is no requirement to further address the source.

3. Based on the tank closure assessment report prepared by Cooper, were there any significant soil impacts detected along the former distribution pipelines running from the 4000 gallon UST to the former pump island?

Unknown. We do not have any information beyond what is contained in the case file.